MATERIAL SAFETY DATA SHEET

PRODUCT NAME: HI BUILD FILLER PUTTY WHITE

HMIS CODES: H

PRODUCT CODE: 467-9

MANUFACTURER'S NAME: SIKKENS AEROSPACE

ADDRESS: 20846 SOUTH NORMANDIE AVENUE, TORRANCE, CA 90502

EMERGENCY PHONE: 213-320-6800

INFORMATION PHONE: 213-320-6800

DATE PREPARED : 07-21-87

NAME OF PREPARER : BRENT BERGMAN

REASON REVISED : ORIGINAL

======= SECTION II - HAZARDOUS INGREDIENTS/IDENTITY INFORMATION ======

	ALO WWAEA	VAPOR PRESSURE			
HAZARDOUS COMPONENTS	UAS NUMBER	ACHIH ILY	OSHA PELY NIOSH PELY	am ny e ienr	
Ethylene glycol monobutyl ether	111-76-2	25 ppm	25 ppm	0.6 68F	10
n-Butyl Acetate	123-86-4	150 pp∎	150 ppm	8.0 68F	(5.0%
Methyl ethyl ketone	78-93-3	200 ppm	200 ppm	75.0 68F	5

========= SECTION III - PHYSICAL/CHEMICAL CHARACTERISTICS

BOILING RANGE: 175 to 340 Deg F VAPOR DENSITY: HEAVIER THAN AIR

SPECIFIC GRAVITY (H20=1): EVAPORATION RATE: SLOWER THAN ETHER

V.O.C.: 3.35 LB/GL (401 GR/LT)

SOLUBILITY IN WATER: INSOLUBLE

APPEARANCE AND ODOR: White liquid Fruity odor

========== SECTION IV → FIRE AND EXPLOSION HAZARD DATA ==========

23 Deg F METHOD USED: T.O.C. FLASH POINT:

FLAMMABLE LIMITS IN AIR BY VOLUME-LOWER: 1.7% UPPER: 11.5%

EXTINGUISHING MEDIA: FOAM, CO2, DRY CHEMICAL

SPECIAL FIREFIGHTING PROCEDURES

Full emergency equipment with self contained breathing apparatus should be worn. During a fire, irritating and highly to xic gases (see reactivity data) and smoke may be present from decomposition/combustion products.

UNUSUAL FIRE AND EXPLOSION HAZARDS

Isolate from heat, electrical equipment, sparks and open flame. Closed container may explode when exposed to extreme hea t. Solvent vapors may be heavier than air. under conditions of stagnant air, vapors may build up and travel along the gr ound to an ignition source which may result in a flash back to the source of the vapors.

STABILITY: STABLE
CONDITIONS TO AVOID
Storage at temperatures above maximum.

INCOMPATIBILITY (MATERIALS TO AVOID) Contamination with strong acids or bases.

HAZARDOUS DECOMPOSITION OR BYPRODUCTS

Fumes produced when heated to decomposition may include: carbon monoxide, carbon dioxide.

HAZARDOUS POLYMERIZATION: WILL NOT OCCUR

INHALATION HEALTH RISKS AND SYMPTOMS OF EXPOSURE

Repeated or prolonged exposure may cause irritation to respiratory tract. Heating may generate vapors that could cause headaches, nausea, dizziness and respiratory irritation if inhaled.

SKIN AND EYE CONTACT HEALTH RISKS AND SYMPTOMS OF EXPOSURE Contains materials that may cause moderate skin injury (reddening and swelling) Can cause allergic skin reaction in certain individuals May cause severe eye injury — damage reversible.

SKIN ABSORPTION HEALTH RISKS AND SYMPTOMS OF EXPOSURE No specific information available. Contains materials that may be slightly toxic.

INGESTION HEALTH RISKS AND SYMPTOMS OF EXPOSURE No specific information available. Contains materials that may be slightly toxic

HEALTH HAZARDS (ACUTE AND CHRONIC)

No specific information available. Contains solvents which are reported to be associated with central nervous system damage after repeated and prolonged exposure. Contains solvents which are reported to cause liver and kidney damage on repeated overexposure.

CARCINOGENICITY: NTP? NO IARC MONOGRAPHS? NO OSHA REGULATED? NO

MEDICAL CONDITIONS GENERALLY AGGRAVATED BY EXPOSURE Chronic lung disease and dermatologic conditions.

EMERGENCY AND FIRST AID PROCEDURES

EYE CONTACT: Flush with clean, lukewarm water (low pressure) for at least 15 minutes., occasionally lifting eye lids. Obtain medical attention.

SKIN CONTACT: Remove contaminated clothing. Wash affected areas thoroughly with soap and water. Wash contaminated clothing thoroughly before reuse.

INHALATION: Move to an area free from risk of further exposure. Administer oxygen or artifical respiration as needed. Obtain medical attention immediately.

INGESTION: Induce vomiting and obtain medical attention immediately.

•							
========	SECTION VII	-	PRECAUTIONS FOR	SAFE	HANDLING	AND USE	=======

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Evacuate all non-essential personnel. Remove all sources of ignition. Ventilate the area. Dike or impound spilled material and control further spillage if feasible. Cover spill with sawdust, vermiculite, Fuller's earth or other absorbant.

WASTE DISPOSAL METHOD

Waste material should be incinerated or disposed of in accordance with Federal, State and local environment control regulations. Empty containers must be handled with care due to product residue. Decontaminate containers prior to disposal. DO NOT HEAT OR CUT EMPTY CONTAINER WITH ELECTRIC OR GAS TORCH.

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

Avoid contamination of skin. Do not apply to hot surfaces or use in areas where exposed to electric sparks. Keep away from fire and open flame. Ground containers when transferring from one to another.

OTHER PRECAUTIONS

=======================================	SECTION VIII	-	CONTROL	MEASURES	=======================================

RESPIRATORY PROTECTION

Wear a properly fitted NIOSH/MSHA approved respirator at all times during exposure to vapors/mists. Where ventilation is inadequate, use full-face air supplied respirator mask.

VENTILATION

Explosion proof mechanical exhaust as required to maintain vapor concentration below lower flammable limit (see Section IV). Not recommended as sole means to control workplace exposure.

PROTECTIVE GLOVES

Impervious (Neoprene) gloves were contact in handling or usage may occur

EYE PROTECTION

Chemical splash goggles.

OTHER PROTECTIVE CLOTHING OR EQUIPMENT

Where contact can occur, a safety shower and eye wash facility should be available.

WORK/HYGIENIC PRACTICES

After contact with material, change clothing and thoroughly wash hands before eating, drinking or smoking.

	Sec. 21		-1 1 5 5 5 A		T	Company of the control of the contro	the control of the co		water all the second
· · · · · · · · · · · · · · · · · · ·	والمنافع والماسالية	أحربا والحارض ويعويهما	a part of supering the same	فقراس كتعادين والمعادين والمهام والمتعاورة	والمحراء فعلان والمعارض	المارجها والمستحدثات	ريد ره نشي شيخ محدوق در در در	and the state of t	
وتساقين تساسم	ه د شستیده	the production of a second contract of	نجستوني بهروة آحم وزاء		an and the contraction of the last of the contract of	يستؤ وبالخواطرة والراران يسافعان	ل البياء والدياسياسية فالكثر بالسوارات والمراجون	a tanka a sa	معاددات والمستحدد المستحدد
						المؤول والمساوي المستوع والمتاسات المساور		ومارا المارا المراه المعاور مريين ميكا والأكلمان والأنبي ميك أوجار والمراز	
	er value and a	for an expension	er e e regeren e en le en en e	प्रशासना स्वरूप्यात स्थान । या १ व्यक्तिका चा	"Space - Augs Secure section of the con-	e gyan e e e e e e e e e e e e e e e e e e e	· we see the control of the see the see of	and the second of the second o	The second secon
			=====	26 26 27 F 16 46		and the second second second	the second of th	e de la companya de	A CONTRACTOR OF THE PARTY OF TH
				==== 🕮 SF	CTTON TY	V	CLATMER ===		Brown and the state of the con-
					-017017 1/	^ =	ULAIMER = ==		
					and the second of the second of				
			a company to the first con-	the region of the state of	the second of th		and the second s		and the second s

DISCLAIMER

The information contained herein is based on the data available to us and is believed to be correct. However, Sikkens Ae rospace makes no warranty, expressed or implied regarding the accuracy of this data or the results to be obtained from the use thereof. Sikkens Aerospace assumes no responsibility for injury from the use of the product described herein.